

Mini STORAGE

12-8-22

1- CAN STILL SEE Light SOURCE
ON BUILDINGS. FLOOD Lamp STILL
ON BUILDING.

2- FENCE FACING WRONG SIDE
TOWARD RESIDENTIAL AREA. DOES
NOT EXTEND FAR ENOUGH.

3- TARP STILL ON FENCE.
SILT FENCE STILL THERE.

James M. Kelly